

ALLISON HYBRID

DPIM UPDATES




Instructor
Led
Training

ALLISON HYBRID H 40/50 EP

DPIM Updates

Release of DPIM2

- The second generation Dual Power Inverter Module (DPIM2) was released in November 2009, beginning with serial number 7210010001.
 - DPIM2 lids include the letters A and B (corresponding to each motor) located just above the AC lug box covers.
 - The DPIM2 Motor A 32-way connector uses a blue Terminal Position Assurance (TPA) retainer rather than the red version used for DPIM1 units.



View PDF View PDF View Graphic View Graphic

1 of 11



ALLISON HYBRID

DPIM UPDATES




Instructor
Led
Training

ALLISON HYBRID H40/50EP

DPIM Updates

Release of DPIM2 (cont'd)

- DPIM1 and DPIM2 are completely interchangeable with an OEM wiring harness modification.
 - The red DPIM1 Motor A 32-way connector TPA is keyed differently and must be replaced with the DPIM2 blue version.
 - Wire functions and pin numbers are the same; only the keying is different between the two TPAs.



View PDF View PDF View Graphic View Graphic



ALLISON HYBRID

DPIM UPDATES



Instructor
Led
Training

ALLISON HYBRID H 40/50 EP


DPIM Updates

Release of DPIM2 (cont'd)

Additional differences:

- DPIM2 units all include the updated cooler port thread design detailed in SIL 21-EP-06.
- DPIM2 uses two rather than four processors; TCM ReFlash will only display EPCU_A and EPCU_B.
- DPIM2 uses different screws to retain the high voltage cables to its bus bars (updated torque is 7-8 Newton Meters or 62-71 inch pounds).

- Reference SIL 21-EP-09 for details.



View PDF View PDF View Graphic View Graphic




ALLISON HYBRID

RESOURCES: Motor A Connector Detail



Instructor
Led
Training

Motor A Connector Detail



RESOURCES

1 of 1



ALLISON HYBRID

RESOURCES: Motor A TPA Replacement




Instructor Led Training

Motor A TPA Replacement

TPA Retainer Change

Disconnect the low voltage 32-way Motor A connector from the DPIM



WARNING: Before attempting to change the TPA retainer ensure that the ignition is in the OFF position and the vehicle knife switch is OPEN. Some of the low voltage terminals will be exposed during this procedure. Care should be taken to ensure that the terminals are not damaged or unseated.

RESOURCES

1 of 4



ALLISON HYBRID

RESOURCES: Motor A TPA Replacement




Instructor Led Training

Motor A TPA Replacement

TPA Retainer Change (cont'd)

Depress both of the retention tabs on both sides of the red TPA retainer



RESOURCES

2 of 4



ALLISON HYBRID

RESOURCES: Motor A TPA Replacement



Instructor Led Training

Motor A TPA Replacement

TPA Retainer Change (cont'd)

Remove the red TPA retainer from the connector



RESOURCES

3 of 4



ALLISON HYBRID

RESOURCES: Motor A TPA Replacement




Instructor Led Training

Motor A TPA Replacement

TPA Retainer Change (cont'd)

Install the blue TPA retainer ensuring that the key seats completely and is retained by both of the retention tabs



RESOURCES

4 of 4



ALLISON HYBRID

DPIM UPDATES




Instructor
Led
Training

DPIM Updates

DPIM2 Software

- All DPIM units are shipped without software – system and diagnostic tool communication requires units to be programmed with software.
 - SIDs are created based on hardware configuration and system application (reference SIL 2-EP-08 for details).
 - The 4th field in the SID identifies the vehicle's hardware configuration based on the Hardware Configuration Chart in SIL 21-EP-09.
 - When replacing a DPIM1 with a DPIM2, the SID must be updated so the 4th field matches the hardware configuration.
 - Example: "F" indicates a MY10 engine, 4th Generation TCM/VCM, DPIM2 and ESS2.



SIL 21-EP-09 Table 1. Hardware Configuration

SID Number	Hardware Configuration			
	Engine	TCM/VCM Type	Inverter Type	Battery Pack
VV X 0 xxx YYY Z	MY06 or earlier	Pre 4th Gen	DPIM1	ESS1
VV X 1 xxx YYY Z	MY07	Pre 4th Gen	DPIM1	ESS1
VV X 2 xxx YYY Z	MY06 or earlier	Pre 4th Gen	DPIM1	ESS2
VV X 3 xxx YYY Z	MY07	Pre 4th Gen	DPIM1	ESS2
VV X 4 xxx YYY Z	MY06 or earlier	Pre 4th Gen	DPIM2	ESS1
VV X 5 xxx YYY Z	MY06 or earlier	Pre 4th Gen	DPIM2	ESS2
VV X 6 xxx YYY Z	MY07	Pre 4th Gen	DPIM2	ESS1
VV X 7 xxx YYY Z	MY07	Pre 4th Gen	DPIM2	ESS2
VV X F xxx YYY Z	MY10	4th Gen	DPIM2	ESS2

4th field in the SID identifies hardware configuration



View PDF



View Graphic

4 of 11



ALLISON HYBRID

DPIM UPDATES




Instructor
Led
Training

DPIM Updates

DPIM2 Software (cont'd)

- Download the new SID as a TCM Assembly Number by adding an "HEV" prefix; for example:
 - A DPIM1 is being replaced with a DPIM2 in a bus with SID 64-G0001-002-U.
 - The TCM Assembly Number is represented by SID fields 3 through 7 (G0001), so the installing technician should log into the PCCS web server and download HEVG4001 using the TCM Assembly Number download option (the "4" in this number is the hardware configuration identifier indicating MY06 or earlier engine; Pre-4th Generation TCM/VCM; DPIM2; ESS1).



SIL 21-EP-09 Table 1. Hardware Configuration

SID Number	Hardware Configuration			
	Engine	TCM/VCM Type	Inverter Type	Battery Pack
VV X 9 xxx YYY Z	MY06 or earlier	Pre 4th Gen	DPIM1	ESS1
VV X 1 xxx YYY Z	MY07	Pre 4th Gen	DPIM1	ESS1
VV X 2 xxx YYY Z	MY06 or earlier	Pre 4th Gen	DPIM1	ESS2
VV X 3 xxx YYY Z	MY07	Pre 4th Gen	DPIM1	ESS2
VV X 4 xxx YYY Z	MY06 or earlier	Pre 4th Gen	DPIM2	ESS1
VV X 5 xxx YYY Z	MY06 or earlier	Pre 4th Gen	DPIM2	ESS2
VV X 6 xxx YYY Z	MY07	Pre 4th Gen	DPIM2	ESS1
VV X 7 xxx YYY Z	MY07	Pre 4th Gen	DPIM2	ESS2
VV X F xxx YYY Z	MY10	4th Gen	DPIM2	ESS2

4th field in the SID identifies hardware configuration



View PDF



View Graphic

5 of 11



ALLISON HYBRID

DPIM UPDATES




Instructor Led Training

DPIM Updates

DPIM2 Software (cont'd)

- Download the new SID as a TCM Assembly Number by adding an "HEV" prefix; for example (cont'd):
 - After installing the DPIM2, the entire vehicle must be reflashed with the updated SID to match the new hardware configuration (other SID fields may change compared to the original, but the hardware field should continue to indicate "4" in this example).



SIL 21-EP-09 Table 1. Hardware Configuration

SID Number	Hardware Configuration			
	Engine	TCM/VCM Type	Inverter Type	Battery Pack
VV X 0 XXX YYY Z	MY06 or earlier	Pre 4th Gen	DPIM1	ESS1
VV X 1 XXX YYY Z	MY07	Pre 4th Gen	DPIM1	ESS1
VV X 2 XXX YYY Z	MY06 or earlier	Pre 4th Gen	DPIM1	ESS2
VV X 3 XXX YYY Z	MY07	Pre 4th Gen	DPIM1	ESS2
VV X 4 XXX YYY Z	MY06 or earlier	Pre 4th Gen	DPIM2	ESS1
VV X 5 XXX YYY Z	MY06 or earlier	Pre 4th Gen	DPIM2	ESS2
VV X 6 XXX YYY Z	MY07	Pre 4th Gen	DPIM2	ESS1
VV X 7 XXX YYY Z	MY07	Pre 4th Gen	DPIM2	ESS2
VV X F XXX YYY Z	MY10	4th Gen	DPIM2	ESS2

4th field in the SID identifies hardware configuration



View PDF



View Graphic



RESOURCES:

DPIM2 Software Configuration Example




Instructor Led Training

DPIM2 Software Configuration Example

DPIM2 Software Configuration Example

Identify the TCM Assembly Number in the SID



RESOURCES

1 of 3



ALLISON HYBRID

RESOURCES:

DPIM2 Software Configuration Example



Instructor Led Training

DPIM2 Software Configuration Example

DPIM2 Software Configuration Example (cont'd)

Use the TCM Assembly Number download option in PCCS to download software based on TCM Assembly Number

Hardware Configuration				
SID Number	Engine	TCM/VCM Type	Inverter Type	Battery Pack
VV X0XXX YYY Z	MY06 or earlier	Pre 4th Gen	DPIM1	ESS1
VV X1XXX YYY Z	MY07	Pre 4th Gen	DPIM1	ESS1
VV X2XXX YYY Z	MY06 or earlier	Pre 4th Gen	DPIM1	ESS1
VV X3XXX YYY Z	MY07	Pre 4th Gen	DPIM1	ESS1
VV X4XXX YYY Z	MY06 or earlier	Pre 4th Gen	DPIM1	ESS1
VV X5XXX YYY Z	MY06 or earlier	Pre 4th Gen	DPIM1	ESS1
VV X6XXX YYY Z	MY07	Pre 4th Gen	DPIM1	ESS1
VV X7XXX YYY Z	MY07	Pre 4th Gen	DPIM1	ESS1
VV XFXXX YYY Z	MY10	4th Gen	DPIM2	ESS2

Add HEV prefix to SID TCM Assembly Number string

Be sure Hardware Configuration Identifier number matches vehicle hardware configuration per chart

Add Calibration to Download Information

Calibration Information

SID: TCM Assembly Number:

Quantity:

Newest Calibration
 Exact Calibration

Calibration for Dyno Usage or Stock TCM/ECU

RESOURCES

2 of 3



ALLISON HYBRID

RESOURCES:

DPIM2 Software Configuration Example



Instructor Led Training

DPIM2 Software Configuration Example

DPIM2 Software Configuration Example (cont'd)

Resulting SID fields may change but Hardware Configuration Identifier number must match vehicle configuration

SID Number	Hardware Configuration			
	Engine	TCM/VCM Type	Inverter Type	Battery Pack
VV X0XXX YYY Z	MY06 or earlier	Pre 4th Gen	DPIM1	ESS1
VV X1XXX YYY Z	MY07	Pre 4th Gen	DPIM1	ESS1
VV X2XXX YYY Z	MY06 or earlier	Pre 4th Gen	DPIM1	ESS2
VV X3XXX YYY Z	MY07	Pre 4th Gen	DPIM1	ESS2
VV X4XXX YYY Z	MY06 or earlier	Pre 4th Gen	DPIM2	ESS1
VV X5XXX YYY Z	MY06 or earlier	Pre 4th Gen	DPIM2	ESS2
VV X6XXX YYY Z	MY07	Pre 4th Gen	DPIM2	ESS1
VV X7XXX YYY Z	MY07	Pre 4th Gen	DPIM2	ESS2
VV XFXXX YYY Z	MY10	4th Gen	DPIM2	ESS2

Original SID: 64-G0001-002-U New SID: VV-G4001-YYY-Z

NOTE: DPIM1 service SIDs are identified by a 1 in the fourth field of the TCM Assembly Number (HEVXXX1X). When downloading a DPIM2 SID, change the 1 to a 0 (HEVXXX0X).

RESOURCES

3 of 3



ALLISON HYBRID

DPIM UPDATES




Instructor
Led
Training

DPIM Updates

DPIM2 Special Tool and Service Kit Updates

- J-46711 Breakout Harness Assembly can be utilized on DPIM2 units by using harness kit J-50165.

- *The harness kit includes two harnesses and a breakout box overlay.*
- *Use kit harness J-50165-1 and J-50165-2 to connect the breakout harness assembly to the DPIM2*
- *Use kit harness J-50165-1 to connect the DPIM Installation Protection Device (DIPD) to the DPIM2.*



NOTE: The DIPD will work with DPIM2 units but is not necessary due to a DPIM2 design change that protects the processors from shorts to battery supply and return at every pin.



View PDF



View Graphic

7 of 11



ALLISON HYBRID

RESOURCES: DPIM Shipping Kit



Instructor
Led
Training

DPIM Shipping Kit

SIL 21-EP-09 Table 2. DPIM2 Shipping Kit, P/N 29550272

Description	P/N	Quantity
Cooler Port Shipping Plug	P/N 29536777	2
A/C Shipping Plug	P/N 29547432	2
D/C Shipping Plug	P/N 29540778	1
24 Way Connector Cover	P/N 29540774	1
32 Way Connector Cover	P/N 29540775	2
Instruction Sheet No. 339	P/N 29550273	1

NOTE: The shipping kit for DPIM1, P/N 29541504, will remain available in case a DPIM1 needs to be removed or shipped. Any time that a DPIM is removed or disconnected for an extended period of time install the shipping plugs and connector covers to prevent contamination.

RESOURCES

1 of 1



ALLISON HYBRID DPIM UPDATES



Instructor
Led
Training

ALLISON HYBRID H40/50EP DPIM Updates

DPIM2 DTCs

- Several new DTCs were added with the introduction of DPIM2.
- SIL 21-EP-09 includes a list of DPIM2-specific DTCs plus some DTCs common to DPIM1 and DPIM2 but with different troubleshooting steps.
- The list includes three tests that apply to both DPIM1 and DPIM2:
 - *Inverter circuit test – IGBT check.*
 - *Inverter circuit test – diode tests.*
 - *Capacitor test.*
- Reference SIL 21-EP-09 Appendix A for details.



View PDF

8 of 11



ALLISON HYBRID

RESOURCES: DPIM2 DTCs

SIL 21-EP-09, Rev. D
 September, 2010
 Product Code(s): 70, 71
 Page 12 of 233



NOTE: This resource link has multiple pages and information changes frequently. Reference the source document for complete, current information.

Appendix A. DPIM DTCs



NOTE: The Appendix B of this SIL replaces Appendix T of the current Troubleshooting Manual TS3715. These new specifications apply to both DPIM1 and DPIM2.

- Inverter Circuit Test — IGBT Check (Page 233)
- Inverter Circuit Test — Diode Tests (Page 233)
- Capacitor Test (Page 233)

Most of the codes and troubleshooting steps in the SIL are specific to DPIM2. However, codes 73-39, 73-41, 74-39, and 74-41 can set for a DPIM1 or a DPIM2, but each DPIM requires different troubleshooting steps. If troubleshooting a DPIM1 with any of these four codes, use the current Troubleshooting Manual. If troubleshooting a DPIM2 with any of these four codes, use the troubleshooting procedure described in this SIL.

Table 3. Diagnostic Trouble Code (DTC) List

DTC Code Description	Light	Restrictive Mode	Failure Record	Page Number
DTC 73-01 (Inverter A PLD Program Error)	Check System	Disable Inverter A, Disable Special Mode	Yes	15
DTC 73-02 (Inverter A Encoder B Power Supply Out-of-Range High)	None	None	Yes	16
DTC 73-03 (Inverter A Boost Internal Supply High)	None	None	Yes	23
DTC 73-04 (Inverter A PLD Heartbeat Error)	Check System	Disable Inverter A, Disable Special Mode	Yes	26
DTC 73-05 (Inverter A Boost Internal Supply Low)	Check System	Disable Inverter A, Disable Special Mode	Yes	27
DTC 73-06 (Inverter A Encoder B Power Supply Out-of-Range Low)	None	None	Yes	30
DTC 73-08 (Inverter A 15V Internal Supply High)	None	None	Yes	37
DTC 73-09 (Inverter A Drive Unit Temperature Circuit)	Check System	Inverter A torque is limited to 70%	Yes	40
DTC 73-10 (Inverter A Phase C, Low IGBT Saturation Fault)	Check System	Disable Inverter A, Disable Special Mode	Yes	45
DTC 73-11 (Inverter A 15V Internal Supply Low)	Check System	Disable Inverter A, Disable Special Mode	Yes	51
DTC 73-16 (Inverter A Phase B, Low IGBT Saturation Fault)	Check System	Disable Inverter A, Disable Special Mode	Yes	54
DTC 73-20 (Inverter A HVIL Short to Ground)	Check System	None	Yes	60
DTC 73-22 (Inverter A Over-current Circuit Error)	None	None	Yes	65
DTC 73-34 (Inverter A Phase C Current Sensor Out-of-Range)	None	None	Yes	66

Copyright 2010 Allison Transmission, Inc. All Rights Reserved.

TECHNICAL PUB

P.O. Box 894 • Indianapolis, Indiana 46206-0894 • (317) 242-5000 • www.allisontransmission.com



ALLISON HYBRID

DPIM UPDATES



Instructor
Led
Training


ALLISON HYBRID H 40/50 EP

DPIM Updates

DPIM High Voltage Lug Bolts

- DPIM1 uses varying fasteners for high voltage lug connection.

- Motors A and B Phase A and Phase C lugs use a 25mm long, plated lug bolt (part of kit 29541537).
- DC positive and negative lugs use a 25mm long, plated lug bolt (part of kit 29541537).
- Motors A and B Phase B lugs use a 45mm long, plated lug bolt (part of kit 29541510).
- Both kits include locking and flat washers to accompany the lug bolts.



View PDF

9 of 11



ALLISON HYBRID

DPIM UPDATES




Instructor
Led
Training

ALLISON HYBRID H 40/50 EP

DPIM Updates

DPIM High Voltage Lug Bolts (cont'd)

- DPIM2 uses a single fastener for all lug bolts.
 - Part number 29548555 is 29mm long with a black oxide finish and captive washers.
- Reference SIL 20-EP-10 for details.



View PDF

10 of 11



ALLISON HYBRID

DPIM UPDATES




Instructor
Led
Training

ALLISON HYBRID H 40/50 EP DPIM Updates

DPIM Cooling System Flush Procedures

- The DPIM should not be flushed if drive unit fluid becomes contaminated.
 - Fluid pressure inside the DPIM is equal to drive unit lube pressure (approx. 4-10 psi).
 - Flush carts often exceed this pressure limit and should never be used to clean contaminated DPIMs.
 - The use of a flushing cart or any type of pressurized flushing equipment risks DPIM internal seal failure resulting in fluid leaks into the DPIM and high voltage lug boxes.
 - As an alternative, Allison recommends removing the DPIM, draining it of all fluid and then reinstalling the DPIM to the vehicle.
- Reference SIL 25-EP-10 for details.

View PDF



Fully draining the DPIM will sufficiently remove contaminants.

11 of 11

