

ALLISON HYBRID

DIAGNOSTICS — TROUBLESHOOTING SCENARIOS




Instructor
Led
Training

ALLISON HYBRID H 40/50 EP Diagnostics — Troubleshooting Scenarios

Required Tools

- Allison DOC for PC (H 40/50 EP) installed on laptop with appropriate translator device.
 - *Version 3.1 and above is required to connect to systems equipped with Allison 4th Generation Controls.*
- Digital volt-ohmmeter.
- Troubleshooting Manual.
- Breakout box with appropriate overlays and harnesses
 - *Harnesses and overlays share the same part number*



1 of 10



ALLISON HYBRID

DIAGNOSTICS — TROUBLESHOOTING SCENARIOS




Instructor
Led
Training

ALLISON HYBRID H 40/50 EP Diagnostics — Troubleshooting Scenarios

Required Tools (cont'd)

- For successful troubleshooting, technicians need to be familiar with the following Allison DOC™ features:

- *Diagnostic Trouble Codes*
- *Failure Records*
- *Data Monitor*
- *ESS Data Monitor*
- *Snapshots*
- *Generating reports*



2 of 10



ALLISON HYBRID

DIAGNOSTICS — TROUBLESHOOTING SCENARIOS




Instructor
Led
Training

ALLISON HYBRID H40/50EP Diagnostics – Troubleshooting Scenarios

Connecting Laptop To Vehicle

- Connect one of the available translator devices to laptop
 - CAN Card 2
 - CANUSB
 - Noregon DLA+ Wireless/USB
 - NEXIQ USB-LINK



View PDF

3 of 10




RESOURCES: Connection Diagram

7. Connecting the PC to the Vehicle

An RP1210A compliant PC-to-vehicle translator is required. Allison DOC ® For PC (H 40/50 EP) currently supports the following translation devices:

- Softing CANusb® (USB port)
- Softing CANCard2® (PCMCIA)
- Softing CAN-AC2_PCI® (PCI bus)
- Nexiq usbLink (version 8.0.5.0 drivers or later)
- Noregon DLA+Wireless

Use the Noregon harness part number 12130 (or 12100) to connect the Softing (or usbLink, DLA+Wireless) translator device to the vehicle connector. The diagram below illustrates the hardware connections between the PC hosting Allison DOC ® For PC (H 40/50 EP), the Softing translator device or usbLink or DLA+Wireless, and the 12130 or 12100 harness.



ALLISON HYBRID

DIAGNOSTICS — TROUBLESHOOTING SCENARIOS



Instructor
Led
Training

ALLISON HYBRID H 40/50 EP Diagnostics – Troubleshooting Scenarios

Connecting The Breakout Box

- Continuity, voltage and resistance checks are often part of troubleshooting procedures.
 - *These are sometimes called “pin out” checks.*
- The breakout box eases pin out check procedures and minimizes the chance of damage to vehicle connectors.
 - *The breakout box installs inline with system components.*
 - *Multiple “overlays” and harnesses are available so the breakout box can be used with the TCM/VCM, DPIM, Drive Unit and ESS.*



Harness J-4725 is required to connect to 4th Gen TCMs

View Video View Video View Video View Graphic View Graphic View Graphic

View Graphic

4 of 10




ALLISON HYBRID

RESOURCES: Breakout Box To TCM Connection



Instructor Led Training

Breakout Box To TCM Connection



Breakout Box to TCM Connection

RESOURCES

1 of 1




ALLISON HYBRID

RESOURCES: Breakout Box To ESS Connection



Instructor
Led
Training

Breakout Box To ESS Connection



Breakout Box to ESS Connection

RESOURCES

1 of 1



ALLISON HYBRID


RESOURCES:

Breakout Box To Drive Unit Connection



Instructor Led Training

Breakout Box To Drive Unit Connection



Breakout Box to Drive Unit Connection

RESOURCES

1 of 1




ALLISON HYBRID

RESOURCES: Breakout Box to DPIM Connection



Instructor Led Training

Breakout Box To DPIM Connection



Breakout Box to DPIM Connection

RESOURCES

1 of 1



ALLISON HYBRID

DIAGNOSTICS — TROUBLESHOOTING SCENARIOS



Instructor
Led
Training

ALLISON HYBRID H 40/50 EP Diagnostics – Troubleshooting Scenarios

Scenario #1

- Diagnostic Codes:
 - 17-21, 44-15, 66-21, 66-33.
- Codes with a 66 prefix are communications codes and should be diagnosed first.
- Use Allison DOC™ to:
 - Verify TCM is commanding signal over wire 323 in the Data Monitor.
 - Verify with the ESS Data Monitor that the ESS is awake and functioning.
- Perform pin out checks at the TCM and ESS with the breakout box.
- Troubleshoot harness wires for continuity problems.



Code 66-21 in the TS Manual indicates starting with code 44-15 if present
Code 44-15 indicates a problem with the ESS Wakeup Signal
Wiring schematic shows TCM wire 323 carrying ESS Wakeup Signal

[View Video](#) [View Video](#) [View Video](#) [View Video](#) [View PDF](#) [View PDF](#) [View PDF](#)

[View Graphic](#)

5 of 10



RESOURCES:

DTC 66-21 CAN Link Lost with Battery Controller



NOTE: This resource link has multiple pages and information changes frequently. Reference the source document for complete, current information.

EP 40/50 SYSTEM™ TROUBLESHOOTING MANUAL

DIAGNOSTIC TROUBLE CODES (DTC)

DTC 66–21 CAN Link Lost with Battery Controller

TCM has detected that the energy storage system is not communicating on the CAN link for more than 240 milliseconds. DTC will not display on the PBSS.

Causes:

- CAN wiring integrity
- Loss of power / intermittent power to ESS

Tool Requirements:

- Universal Electronic Breakout Box (J-39700)
- Breakout Harness (J-46711)
- Breakout Harness (J-46712)
- Multimeter
- Allison DOC™ For PC (AED)

Table 5–137. DTC 66–21 CAN Link Lost With Battery Controller

Step	Action	Value(s)	Yes	No
1	Was the code logged in conjunction with DTC 44–15?		Follow troubleshooting procedure for DTC 44-15	Go to Step 2
2	Was DTC 66–21 logged in conjunction with DTC 42–15?		Follow troubleshooting procedure for DTC 42-15	Go to Step 3
3	Is the DTC active?		Go to Step 5	Go to Step 4
4	Is there a vehicle performance complaint?		Go to Step 5	Clear code. Go to Step 15
5	Check that all of the connectors are clean, the pins are good, and that their seals are intact. Clear codes. Do the codes reappear?		Go to Step 6	Go to Step 15
6	Check for +12V on pins F and P on the ESS 31-pin connector. Check for continuity to ground on pins G, H, and Z on the ESS 31-pin connector. Is the wake-up signal acceptable?		Go to Step 8	Make repairs as necessary. If DTC returns, go to Step 8; otherwise, go to Step 15
7	Check for ground wake-up signal on pin L of the ESS 31-pin connector. Is the wake-up signal acceptable?		Go to Step 8	Make repairs as necessary. If DTC returns go to Step 8; otherwise, go to Step 15



RESOURCES:

DTC 44-15 Battery Controller Wake-Up Open or Short-to-Ground



NOTE: This resource link has multiple pages and information changes frequently. Reference the source document for complete, current information.

EP 40/50 SYSTEM™ TROUBLESHOOTING MANUAL

DIAGNOSTIC TROUBLE CODES (DTC)

DTC 44–15 Battery Controller Wake-up Open Or Short-to-Ground

If wire 323 is open, the code may be accompanied by CAN link lost with Battery Controller (DTC 66–21 and 66–33).

If wire 323 is shorted to ground, the ESS system controllers will remain on.

Complaints:

- Stopped vehicle (unable to start engine) if open
- Low 12V Battery if short-to-ground

Cause:

- Bad wiring or connectors

Tool Requirements:

- Universal Electronic Breakout Box (J-39700)
- Breakout Harness (J-46711)
- Breakout Harness (J-46712)
- Multimeter
- Allison DOC™ For PC (AED)
 - Action Requests → Output Tests → Energy Storage Wake-up On

Table 5–95. DTC 44–15 Battery Controller Wake-up Open Or Short-to-Ground

Step	Action	Value(s)	Yes	No
1	Is the code active?		<i>Go to Step 3</i>	<i>Go to Step 2</i>
2	Is there a driver complaint? DTC 66–33 will often be logged in conjunction with DTC 44–15, resulting in a Check System light.		<i>Go to Step 3</i>	<i>Possible intermittent fault.</i>
3	Connect Allison DOC™ For PC (AED) to the vehicle. Clear DTCs. Using the Action Requests → Output Tests → Energy Storage Wake-up On, turn Energy Storage Wake-up On ON and OFF , and see if the DTC comes back as active. Did DTC 44–15 return active, or did the Output Test fail to complete?		<i>Go to Step 4</i>	<i>Intermittent fault. Go to Step 4</i>
4	Be sure the harness is tightly connected. If connected properly, disconnect the wiring harness at the TCM and the Energy Storage System and check the connectors for corroded or damaged terminals. Clean or replace as necessary. Were any repairs made?		<i>Go to Step 7</i>	<i>Go to Step 5</i>



ALLISON HYBRID

RESOURCES: Wiring Schematic

APPENDIX H—EP 40/50 SYSTEM™ WIRING SCHEMATIC




Figure H-1. Allison Electric Drive™ Wiring Schematic—TCM

* WIRE CLASSES ARE DEFINED AS FOLLOWS:
 E = 12V BATTERY
 F = 12V BATTERY
 G = 12V BATTERY
 H = 12V BATTERY
 I = 12V BATTERY
 J = 12V BATTERY
 K = 12V BATTERY
 L = 12V BATTERY
 M = 12V BATTERY
 N = 12V BATTERY
 O = 12V BATTERY
 P = 12V BATTERY
 Q = 12V BATTERY
 R = 12V BATTERY
 S = 12V BATTERY
 T = 12V BATTERY
 U = 12V BATTERY
 V = 12V BATTERY
 W = 12V BATTERY
 X = 12V BATTERY
 Y = 12V BATTERY
 Z = 12V BATTERY

WIRE CLASSES ARE DEFINED AS FOLLOWS:
 A = 12V BATTERY
 B = 12V BATTERY
 C = 12V BATTERY
 D = 12V BATTERY
 E = 12V BATTERY
 F = 12V BATTERY
 G = 12V BATTERY
 H = 12V BATTERY
 I = 12V BATTERY
 J = 12V BATTERY
 K = 12V BATTERY
 L = 12V BATTERY
 M = 12V BATTERY
 N = 12V BATTERY
 O = 12V BATTERY
 P = 12V BATTERY
 Q = 12V BATTERY
 R = 12V BATTERY
 S = 12V BATTERY
 T = 12V BATTERY
 U = 12V BATTERY
 V = 12V BATTERY
 W = 12V BATTERY
 X = 12V BATTERY
 Y = 12V BATTERY
 Z = 12V BATTERY

CONNECTOR PIN NUMBERS SHOWN ARE MAINS
 MATE CONNECTOR PIN NUMBERS SHOWN ARE
 MATE CONNECTOR PIN NUMBERS SHOWN ARE
 MATE CONNECTOR PIN NUMBERS SHOWN ARE
 MATE CONNECTOR PIN NUMBERS SHOWN ARE

REFER TO ALLISON TECHNICAL DOCUMENT NO. 89
 FOR INFORMATION ON WIRING IDENTIFICATION

WIRING IDENTIFICATION
 WIRING IDENTIFICATION
 WIRING IDENTIFICATION
 WIRING IDENTIFICATION

ALLISON HYBRID

RESOURCES: Wiring Schematic

APPENDIX H—EP 40/50 SYSTEM™ WIRING SCHEMATIC




Figure H-2. Allison Electric Drive™ Wiring Schematic—VCM


WIRE #	RECOMMENDED COLOR	CLASS*	DESCRIPTION
102-PW1.1	YELLOW	D	IGNITION
102-PW1.2	YELLOW	E	+VE BATTERY
102-PW1.3	RED	F	IGNITION
102-PW1.4	YELLOW	D	IGNITION
102-PW1.5	YELLOW	D	IGNITION
102-PW1.6	WHITE	A	ENGINE SHIFTER REQUEST
102-PW1.7	ORANGE	A	ACCELERATOR WALK
102-PW1.8	ORANGE	A	ACCELERATOR WALK S2
102-PW1.9	BLUE	C	AUTOMATIC NEUTRAL
102-PW1.10	BLUE	C	AUTOMATIC NEUTRAL
102-PW1.11	BLUE	B	SHIFT SELECTOR WALK/ROBE
102-PW1.12	BLUE	B	SHIFT SELECTOR WALK/ROBE
102-PW1.13	NAVY	B	SYSTEM OVERDRIE REQUEST
102-PW1.14	NAVY	B	SYSTEM OVERDRIE REQUEST
102-PW1.15	NAVY	B	SYSTEM OVERDRIE REQUEST
102-PW1.16	NAVY	B	SYSTEM OVERDRIE REQUEST
102-PW1.17	WHITE	A	BRAKE EXHAUSTION
102-PW1.18	NAVY	B	WALK/ROBE REQUEST
102-PW1.19	NAVY	B	WALK/ROBE REQUEST
102-PW1.20	ORANGE	C	SHIFT SELECTOR WALK/ROBE
102-PW1.21	ORANGE	C	SHIFT SELECTOR WALK/ROBE
102-PW1.22	GREEN	C	STOP SYSTEM INDICATOR
102-PW1.23	GREEN	C	STOP SYSTEM INDICATOR
102-PW1.24	ORANGE	C	SYSTEM OVERDRIE INDICATOR
102-PW1.25	RED	C	SYSTEM OVERDRIE INDICATOR
102-PW1.26	RED	C	REVERSE WARNING
102-PW1.27	BLUE	B	SHIFT SELECTOR SERIAL DATA LINK
102-PW1.28	YELLOW	A	IGNITION
102-PW1.29	YELLOW	A	IGNITION
102-PW1.30	BLACK	A	IGNITION
102-PW1.31	BLACK	A	IGNITION
102-PW1.32	BLUE	B	HIGH/LOW RANGE REQUEST
102-PW1.33	BLUE	B	HIGH/LOW RANGE REQUEST
102-PW1.34	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.35	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.36	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.37	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.38	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.39	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.40	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.41	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.42	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.43	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.44	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.45	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.46	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.47	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.48	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.49	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.50	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.51	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.52	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.53	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.54	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.55	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.56	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.57	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.58	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.59	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.60	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.61	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.62	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.63	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.64	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.65	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.66	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.67	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.68	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.69	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.70	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.71	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.72	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.73	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.74	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.75	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.76	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.77	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.78	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.79	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.80	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.81	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.82	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.83	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.84	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.85	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.86	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.87	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.88	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.89	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.90	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.91	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.92	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.93	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.94	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.95	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.96	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.97	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.98	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.99	NAVY	B	ACCELERATOR WALK/ROBE REQUEST
102-PW1.100	NAVY	B	ACCELERATOR WALK/ROBE REQUEST

* WIRE NUMBERS SHOWN IN SCHEMATIC CORRELATE TO THE WIRE NUMBERS SHOWN IN THE WIRING SCHEMATIC. WIRE COLORS ARE REFERRED TO BY LETTERS (OR NUMBERS) IN PARENTHESES. WHEN RELATES ARE NOT LISTED, ALL WIRING CONNECTIONS ARE CUSTOMER SPECIFIED. REFER TO ALLISON TECHNICAL DOCUMENT 189 FOR WIRING CONNECTIONS ON REMANUFACTURED UNITS.

ALLISON HYBRID

RESOURCES: Wiring Schematic

APPENDIX H—EP 40/50 SYSTEM™ WIRING SCHEMATIC



ALLISON HYBRID

RESOURCES: Wiring Schematic

APPENDIX H—EP 40/50 SYSTEM™ WIRING SCHEMATIC




Figure H-5. Allison Electric Drive™ Wiring Schematic—HVIL


ALLISON HYBRID

RESOURCES: Isolated Schematic



Instructor
Led
Training

Isolated Schematic



RESOURCES

1 of 1



ALLISON HYBRID

DIAGNOSTICS — TROUBLESHOOTING SCENARIOS



Instructor
Led
Training

ALLISON HYBRID H40/50EP Diagnostics – Troubleshooting Scenarios

Scenario #2

- Diagnostic Codes:
 - 25-20, 44-19, 66-18, 66-19, 66-31, 66-32, 80-32.
- Codes with a 66 prefix are communications codes and should be diagnosed first.
- Use Allison DOC™ to:
 - Verify a missing wakeup signal.
- Perform pin out checks at the TCM and DPIM with the breakout box.
- Troubleshoot harness wires and relays for continuity problems.



Code 66-18 in the TS Manual indicates starting with code 44-19 if present
Code 44-19 indicates a problem with TCM side of inverter wake-up relay
Wiring schematic shows TCM wire 428 carrying DPIM Wakeup Signal

- View Video
- View Video
- View Video
- View Video
- View PDF
- View PDF
- View PDF
- View Graphic

6 of 10



RESOURCES:

DTC 66-18 CAN Link Lost with Inverter A



NOTE: This resource link has multiple pages and information changes frequently. Reference the source document for complete, current information.

E^P 40/50 SYSTEM™ TROUBLESHOOTING MANUAL

DIAGNOSTIC TROUBLE CODES (DTC)

DTC 66–18 CAN Link Lost With Inverter A

TCM has detected that Inverter A is not communicating on the CAN link for more than 120 milliseconds. The DTC will not be displayed on the PBSS.

Causes:

- CAN wiring integrity
- Loss of power / intermittent power to DPIM

Tool Requirements:

- Universal Electronic Breakout Box (J-39700)
- Breakout Harness (J-46711)
- Multimeter
- Allison DOC™ For PC (AED)

Table 5–135. DTC 66–18 CAN Link Lost With Inverter A

Step	Action	Value(s)	Yes	No
1	Was the code logged in conjunction with DTC 44–19?		Follow troubleshooting procedure for DTC 44-19. DTC indicates a problem with the wake-up on the TCM side of the relay	Go to Step 2
2	Was the code logged in conjunction with DTC 42–19?		Follow troubleshooting procedure for DTC 42-19. DTC indicates a problem with the wake-up on the TCM side of the relay	Go to Step 3
3	Is the DTC active?		Go to Step 5	Go to Step 4
4	Is there a customer complaint of disabled propulsion?		Go to Step 5	Clear code. Go to Step 15
5	Check that all of the connectors are clean, the pins are good, and that their seals are intact. Clear codes. Do the codes re-appear?		Go to Step 6	Go to Step 15
6	Check for +12V on pins 1, 2, 5, and 6 on the DPIM 24-pin connector. Check for continuity to ground on pins 18, 19, 20, and 21 on the DPIM 24-pin connector. Are both 12V and ground connections acceptable?		Go to Step 7	Make repairs as necessary. If DTC returns, go to Step 7; otherwise, go to Step 15



RESOURCES:

DTC 44-19 Inverter Wake Up Open or Short-to-Ground



NOTE: This resource link has multiple pages and information changes frequently. Reference the source document for complete, current information.

E^P 40/50 SYSTEM™ TROUBLESHOOTING MANUAL

DIAGNOSTIC TROUBLE CODES (DTC)

DTC 44–19 Inverter Wake Up Open Or Short-to-Ground

If DTC 44–19 is associated with an open in the circuit, CAN link lost with Inverter controller A (DTCs 66–18 and 66–31) and Inverter controller B (DTCs 66–19 and 66–32) is expected. A short-to-ground may result in DPIM controllers remaining on.

Complaints:

- Vehicle propulsion disabled
- Low 12V if the problem is a short-to-ground

NOTE: If DTC 44–19 is active at start-up and DTC 66–18 and 66–19 accompanies code, vehicle will not start.

NOTE: If DTC 44–19 occurs while driving, vehicle will continue to drive until the vehicle is keyed off.

Cause:

- Bad wiring or connectors

Tool Requirements:

- Universal Electronic Breakout Box (J-39700)
- Breakout Harness (J-46711)
- Multimeter
- Allison DOC™ For PC (AED)
 - Action Requests → Output Tests → Inverter Wake-up A and B

Table 5–99. DTC 44–19 Inverter Wake-up Open Or Short-to-Ground

Step	Action	Value(s)	Yes	No
1	Is the code active?		Go to Step 3	Go to Step 2
2	Is there a driver complaint? (DTC 66–31 and 66–32 will often be logged in conjunction with this code, both of which cause a Check System light)		Go to Step 3	Possible intermittent code. Go to Step 3
3	Connect Allison DOC™ For PC (AED) to the vehicle. Clear DTCs. Using the Action Requests → Output Tests → Inverter Wake-up A and B, turn Inverter Wake-up A and B ON and OFF , and see if the DTC comes back as active. Did DTC 44–19 return active, or did the Output Test fail to complete?		Go to Step 4	Intermittent fault. Go to Step 4
4	Be sure the harness is tightly connected. If connected properly, disconnect the low voltage wiring harnesses at the TCM and the DPIM and check the connectors for corroded or damaged terminals. Clean or replace as necessary. Were any repairs made?		Go to Step 7	Go to Step 5




ALLISON HYBRID

RESOURCES: Isolated Schematic



Instructor
Led
Training

Isolated Schematic



RESOURCES

1 of 1



ALLISON HYBRID

DIAGNOSTICS — TROUBLESHOOTING SCENARIOS



Instructor
Led
Training

ALLISON HYBRID H40/50EP Diagnostics – Troubleshooting Scenarios

Scenario #3

- Diagnostic Code:
 - 73-32.
- Use Allison DOC™ Data Monitor to view Motor A and B Temperature.
- Use the breakout box to perform pin out checks at the DPIM and Drive Unit.
- Use continuity checks to troubleshoot harness wires and relays.



The TS Manual recommends checking temperature values for Motors A & B

View Video

View Video

View Video

View Video

View PDF

View PDF

7 of 10



ALLISON HYBRID


RESOURCES: DTC 73-32 Inverter A Motor Temperature Out-of-Range High

NOTE: This resource link has multiple pages and information changes frequently. Reference the source document for complete, current information.


E^P 40/50 SYSTEM™ TROUBLESHOOTING MANUAL

DIAGNOSTIC TROUBLE CODES (DTC)

DTC 73-32 Inverter A Motor Temperature Out-of-Range High



Resistance vs. Temperature



Chassis Harness



ALLISON HYBRID

DIAGNOSTICS — TROUBLESHOOTING SCENARIOS



Instructor
Led
Training

ALLISON HYBRID H40/50EP Diagnostics – Troubleshooting Scenarios

Scenario #4

- Diagnostic Code:
 - 76-61.
- Reference SIL 10-EP-10:
 - ESS Refresh Kit was applied to an installed ESS1 to convert it to an ESS2.
 - Software level E27 was not loaded into BCIMs after Refresh Kit was installed.
- Diagnostic Procedure:
 - Download new system calibration.
 - Use TCM Reflash to install calibration into the system.
 - Verify calibration loaded properly.
 - Start the vehicle and verify proper operation.



View Video View Video View PDF View PDF View PDF

8 of 10



RESOURCES:

DTC 76-61 Battery Subpack Software ID

E^P 40/50 SYSTEM™ TROUBLESHOOTING MANUAL

DIAGNOSTIC TROUBLE CODES (DTC)

DTC 76–61 Battery Subpack Software ID

This code is triggered at start-up if any one of the BCIMs has a different software version than the rest of the controllers. Refer to the troubleshooting procedures for DTC 34–25.

Table 5–264. DTC 76–61 Battery Subpack Software ID

Step	Action	Value(s)	Yes	No
1	Is the code active?		<i>Refer to troubleshooting procedures for DTC 34–25</i>	<i>Contact AED Service Engineering</i>

NOTE: For additional troubleshooting procedures, refer to the *Energy Storage System Service and Troubleshooting Manual (SM4162EN)*.



RESOURCES:

DTC 34-25 BCIM Calibration ID Number Mismatch

E^P 40/50 SYSTEM™ TROUBLESHOOTING MANUAL

DIAGNOSTIC TROUBLE CODES (DTC)

DTC 34–25 BCIM Calibration ID Number Mismatch

Cause:

- Software/calibration incompatibility. Incorrect component software or calibration loaded.

Complaint:

- Vehicle shutdown

Tool Requirement:

- TCM Reflashing Tool

Table 5–69. DTC 34–25 BCIM Calibration ID Number Mismatch

Step	Action	Value(s)	Yes	No
1	Determine the correct SID for the vehicle. Have you determined the correct SID?		<i>Go to Step 2</i>	<i>Contact Allison Service Engineering for correct SID and then go to Step 2</i>
2	Connect TCM Reflashing Tool to the vehicle and recalibrate the entire system with the correct SID. Did the code return?		<i>Go to Step 3</i>	<i>System OK</i>
3	Is it only one code?		<i>Go to Step 4</i>	<i>Go to Step 5</i>
4	Exchange controller that is triggering the code and recalibrate the vehicle. Is this step complete?		<i>Go to Step 6</i>	
5	If all of the codes have been triggered, swap out the TCM and recalibrate the vehicle. Is this step complete?		<i>Go to Step 6</i>	
6	In order to verify your repair: 1. Clear the DTC. 2. Did the DTC return?		<i>Begin the diagnosis again. Go to Step 1</i>	<i>System OK</i>



ALLISON HYBRID

DIAGNOSTICS — TROUBLESHOOTING SCENARIOS



Instructor
Led
Training

ALLISON HYBRID H40/50EP Diagnostics – Troubleshooting Scenarios

Scenario #5

- Diagnostic Codes:
 - 23-14, 23-15, 23-18.
- Vehicle is equipped with Allison 4th Generation Controls.
- Use SIL 20-EP-09 to troubleshoot.
- Use Allison DOC™ to:
 - Verify missing PBSS signal.
- Perform pin out checks at the PBSS wiring harness.
- Troubleshoot CAN Bus for problems.



Code 23-18 indicates PBSS signal loss of both CAN and PWM signals. SIL 20-EP-09, Appendix C indicates wire 350 is used for PBSS wakeup signal on a 4th Gen TCM.

- View Video
- View Video
- View Video
- View Video
- View PDF
- View PDF
- View PDF
- View Graphic
- View PDF
- View PDF

9 of 10



RESOURCES:

DTC 23-14 PBSS PWM Input Fault (No Range Info from PWM)




NOTE: This resource link has multiple pages and information changes frequently. Reference the source document for complete, current information.



SIL 20-EP-09, Rev. A
 June, 2010
 Product Code(s): 70, 71
 Page 12 of 135

DTC 23-14 PBSS PWM Input Fault (No Range Info from PWM)

END VIEW OF 16-WAY PBSS CONNECTOR



END VIEW OF 80-WAY CONNECTOR



V20254.00.00

Overview:

Allison 4th Generation Controls shift selectors communicate with the Transmission Control Module (TCM) by exchanging standardized digital messages over the SAE J1939 Controller Area Network (CAN). The shift selectors are also equipped with a single wire backup to the J1939 CAN data link. Allison 4th Generation shift selectors transmit directional information (Forward, Neutral, and Reverse) in the form of an analog pulse-width modulated (PWM) signal via wire 334 to the TCM. The shift selector switches an internal driver **ON** and **OFF** to vary the duty cycle of the voltage on wire 334. When the driver in the shift selector is **ON**, the voltage on wire 334 is pulled to ground. When the driver is **OFF**, the driver's output is open and the voltage on wire 334 is high. Since duty cycle is measured when voltage is high, the driver's **OFF**-time determines the duty cycle. For example, if wire 334 duty cycle is 15 percent, the shift selector driver is **ON** (pulled low) 85 percent of the time and **OFF** (open) 15 percent of the time.

Actions Taken When DTC Sets:

When DTC 23-14 is active, the following conditions will occur:

- Check System light illuminates



RESOURCES:


DTC 23-15 PBSS CAN Fault (No Range Info from CAN)



NOTE: This resource link has multiple pages and information changes frequently. Reference the source document for complete, current information.

SIL 20-EP-09, Rev. A
 June, 2010
 Product Code(s): 70, 71
 Page 16 of 135

DTC 23-15 PBSS CAN Fault (No Range Info from CAN)



99796

Overview:

The Push Button Shift Selector (PBSS) sends range selection data to the TCM via CAN communication. The PBSS also sends the range selection data to the TCM via a redundant PWM signal. PBSS TC1 fault means that no valid range could be determined from the TC1 message or that the TC1 message has timed out. CAN Link Lost with the PBSS or invalid CAN data.

Actions Taken When DTC Sets:

When DTC 23-15 is active, the following conditions will occur:




RESOURCES:

DTC 23-18 Communication Fault (No Range Info from CAN or PWM)

SIL 20-EP-09, Rev. A
 June, 2010
 Product Code(s): 70, 71
 Page 20 of 135

NOTE: This resource link has multiple pages and information changes frequently. Reference the source document for complete, current information.

DTC 23-18 PBSS Communication Fault (No Range Info from CAN or PWM)



99796

Overview:

The Push Button Shift Selector (PBSS) sends range selection data to the TCM via CAN communication. The PBSS also sends the range selection data to the TCM via a redundant Pulse Width Modulated (PWM) signal. PBSS Communication fault means that no valid range could be determined from either the CAN signal or the PWM backup signal.

This code will set when DTC 23-14 and DTC 23-15 are active.




ALLISON HYBRID

RESOURCES: Isolated Schematic



Instructor Led Training

Isolated Schematic



RESOURCES

1 of 1



RESOURCES:

Allison Hybrid Wiring Reference Tables

NOTE: This resource link has multiple pages and information changes frequently. Reference the source document for complete, current information.

SIL 20-EP-09, Rev. A
June, 2010
Product Code(s): 70, 71
Page 126 of 135

Appendix C. AED Wiring Reference Tables

Table 6. TCM

DESCRIPTION	PRE 4TH GEN CONNECTOR	PRE 4TH GEN GM WIRE NO.	PRE 4TH GEN WIRE NO.	PRE 4TH GEN PIN NO.	4TH GEN WIRE NO.	4TH GEN PIN NO.
+12V BATTERY RETURN	Gray TCM	138-PT13-1	301	1	309	9
IGNITION	Gray TCM	101B-PT13-2	302	2	363	63
+12V BATTERY	Gray TCM	139-PT13-3	303	3	310	10
+12V BATTERY	NA	NA	NA	NA	370	70
IGNITION	Gray TCM	101C-PT13-4	304	4	NA	NA
TCM ID (+12V BATTERY RETURN)	Gray TCM	252-PT13-11	311	11	362	62
ESS PRE-TUNNEL CHARGE	Gray TCM	255-PT13-6	306	6	323	23
STATION MODE	Gray TCM	240-PT13-7	307	7	302	2
FRONT OPERATION MODE 1	Gray TCM	143-PT13-8	308	8	343	43
FRONT OPERATION MODE 2	Gray TCM	144-PT13-9	309	9	322	22
+12V BATTERY RETURN	Gray TCM	140-PT13-5	305	5	362	62
FAST IDLE	Gray TCM	145-PT13-12	312	12	342	42
AUX FUNCTION RANGE INHIBIT	Gray TCM	220-PT13-13	313	13	301	1
ENERGY STORAGE RELAY CLOSED	Gray TCM	146-PT13-14	314	14	379	79
OIL LEVEL SENSOR SIGNAL	Gray TCM	147-PT13-15	315	15	316	16
OIL LEVEL SENSOR EXCITATION (SUPPLY)	Gray TCM	148-PT13-17	317	17	312	12
OIL LEVEL SENSOR RETURN (ANALOG RETURN)	Gray TCM	170-PT14-20	420	20	358	58
AUX BRAKE INDICATOR	Gray TCM	150-PT13-20	320	20	304	4
OUTPUT SPEED INDICATOR	Gray TCM	151-PT13-22	322	22	345	45
ENERGY STORAGE WAKEUP	Gray TCM	152-PT13-23	323	23	305	5
ENGINE WAKEUP	Gray TCM	153-PT13-24	324	24	324	24
SPEEDOMETER SIGNAL	Gray TCM	154-PT13-26	326	26	325	25
CAN HI	Gray TCM	155-PT13-29	329	29	328	28
CAN SHIELD	Gray TCM	156-PT13-31	331	31	349	49
CAN LO	Gray TCM	157-PT13-32	332	32	308	8
C1 PRESSURE SWITCH	Red TCM	158-PT14-1	401	1	357	57
FAST IDLE 2	Red TCM	160-PT14-5	405	5	361	61



ALLISON HYBRID

RESOURCES: TCM 4th Generation Wiring

Appendix D. 4th Gen Wiring




Figure 8. TCM 4th Generation Wiring

ALLISON HYBRID

RESOURCES: VCM 4th Generation Wiring




Figure 9. VCM 4th Generation Wiring

ALLISON HYBRID

RESOURCES: DPIM 4th Generation Wiring




Figure 10. DPIM 4th Generation Wiring

ALLISON HYBRID

RESOURCES: ESS 4th Generation Wiring




Figure 11. ESS 4th Generation Wiring

ALLISON HYBRID

RESOURCES: CAN & PBSS 4th Generation Wiring




Figure 12. CAN 4th Generation Wiring




Figure 13. PBSS 4th Generation Wiring

ALLISON HYBRID

DIAGNOSTICS — TROUBLESHOOTING SCENARIOS



Instructor
Led
Training

ALLISON HYBRID H40/50EP Diagnostics – Troubleshooting Scenarios

Scenario #6

- Diagnostic Codes:
 - 66-40.
- Vehicle is equipped with Allison 4th Generation Controls.
- Use SIL 20-EP-09 to troubleshoot.
- Use Allison DOC™ to:
 - Clear code and verify it remains active
- Use TCM Reflash to reload system calibration.
- Inspect wiring at the Drive Unit fan controller.
- Perform CAN bus resistance checks.



Code 66-40 indicates CAN signal loss to OEM installed Drive Unit fan controller.

- View Video
- View Video
- View Video
- View Video
- View PDF
- View Graphic
- View PDF
- View PDF

10 of 10



RESOURCES:

DTC 66-40 CAN Link Lost with Fan Drive Controller



NOTE: This resource link has multiple pages and information changes frequently. Reference the source document for complete, current information.

SIL 20-EP-09, Rev. A
June, 2010
Product Code(s): 70, 71
Page 118 of 135

DTC 66-40 CAN Link Lost with Fan Drive Controller

Overview:

TCM has detected that the Fan Drive Controller is not communicating on the CAN link.

Actions Taken When DTC Sets:

- None

Causes:

- Loss of power or ground to the fan drive controller
- Incorrect SID
- CAN Wiring Integrity

Tool Requirements:

- Allison DOC® For PC (AED)
- J-39700 Universal Electronic Breakout Box
- J-47275 Breakout Harness 4th Gen TCM/VCM
- J-46708 Multimeter

Step	Action	Value(s)	Yes	No
1	1. Install Allison DOC® For PC (AED). 2. Start the engine. 3. Record the DTC failure record data. 4. Monitor TCM ignition voltage. Is the voltage within the specified values?	9–18V	Go to Step 3	Resolve voltage problem. Go to Step 11
2	Is code 66-40 active?		Go to Step 4	Go to Step 3
3	1. Clear the DTC. 2. Attempt to duplicate the conditions in the failure record (mode, temperature, etc.) Does code 66-40 return?		Go to Step 4	System OK
4	Determine the correct SID for the vehicle. Does the vehicle contain the correct SID?		Go to Step 6	Go to Step 5
5	Connect TCM Reflashing Tool to the vehicle and recalibrate the entire system with the correct SID. Was the entire vehicle reflash successful?		Go to Step 11	Attempt a single device load for any components that failed to load.




ALLISON HYBRID

RESOURCES: Isolated Schematic



Instructor Led Training

Isolated Schematic



RESOURCES

1 of 1

